KC HiLiTES 10 in. C-Series C10 LED Light Bar - Spot/Spread Combo

Installation Guide for Jeep Wrangler '07-'18 4-Door JKU

Installation Time: <1 Hour

Tools Required:

Installation Instructions:

1. Remove the wiring harness from the box and locate the battery terminal connects (Figure A).

Figure A

2. Run the positive (red) wire to the positive (+) battery terminal under the hood (Figure B).

3. Run the negative (black) wire to the negative (-) battery terminal under the hood (Figure C).

Figure C

4. Run the wiring harness through the firewall to the mounting location and connect the white wire to the bottom switch terminal (supplied) (Figure D).

Figure D

5. Connect the blue wire to the middle switch terminal (Figure E).

Figure E

6. Connect the black (ground) wire to the top switch terminal (Figure F).

Figure F

7. Tighten the mounting legs onto the LED light bar using the supplied bolts and Allen wrench (Figure G).

Figure G

8. Run the wiring harness connect to the LED light bar mounting location (Figure H).

Figure H

9. Connect the LED light bar to the wiring harness (Figure I).

Figure I

Before

After

Installation Instructions Written by ExtremeTerrain Customer J. Sandlin 08/24/2018