Rigid Industries Ignite Backup Light Kit

Installation Guide for Jeep Wrangler '07-'18 4-Door JKU

Installation Time: <1 Hour

Tools Required:

- ✓ Box Cutter/Knife (Packaging)
- ✓ Allen Wrench
- ✓ GoPro Mount
- ✓ Light Harness

Installation Instructions:

1. Open the packaging and locate the bolt which cross-threads the mounting location (Figure A).

Figure A

2. Set the light onto the GoPro mount (not included) (Figure B).

Figure B

3. Place the bolt in the cross-threading location of the GoPro mount (Figure C).

Figure C

4. Using an Allen wrench, tighten the bolt into the mount (Figure D).

Figure D

5. Connect the red (positive) wire to the positive of a light harness (Figure E).


Figure E

6. Connect the black (ground) wire to the ground of a light harness (Figure F).

Figure F

7. Mount the light in the location desired (Figure G).

Figure G

8. Locate the light connector and light harness (Figure H).

Figure H

9. Connect the light to the wiring harness (Figure I).

Figure I

10. Repeat Steps 2-9 for the second light.

Before

After

Installation Instructions Written by ExtremeTerrain Customer J. Sandlin 08/15/2018