

JK Billet Aluminum Washer Fluid Cap 07-11




Contents: Washer Fluid Cap (1)


PLEASE READ AND UNDERSTAND ALL INSTRUCTIONS BEFORE YOU BEGIN.

Notice: Aluminum holds more heat than plastic. Use caution when removing.

Step 1. Remove the factory washer fluid cap from the reservoir. Clean area around cap.



Step 2. Install the retainer wire around the neck of the tank first. Install the new billet cap onto the reservoir.



Care and Maintenance: Use soap and water to clean the aluminum surface. Regular cleaning with help maintain the appearance. Do not use harsh chemicals.

For Technical Assistance Contact:
OMIX-ADA Tech Support
Phone: 1-800-449-6649
Email: techsupport@omix-ada.com
Web: www.Omix-Ada.com

Copyright Omix-Ada 2011